



CAR FREE DAY MALIOBORO



Syarief Teguh Prabowo. SSTP






The main challenge to be addressed



1. Unorganized Street vendor
2. Limited Area of CFD (25% of Malioboro Street)
3. There are no policy and regulation yet



Communities





Optimation of Margo Mulyo Roads as a Car Free Day Area and Pedestrian Walk

1

Zero Point has been sterilized from street vendor

2

Equipped with street supporting facilities e.g. Street lamp and bench

3

Used as cultural and art activities integrated with Vredeburg Fortress





Optimation of Margo Mulyo Roads as Pedestrian Walk



Traffic Circulation



- ❖ Road Traffic Diversion:
from Jl Suryatmajan &
Jl Pajeksan
- ❖ Large Vehicles (bus)
directed to stand away
from Malioboro to Jl
Suryatmajan
- ❖ Organize the parking
area on Jl. Suryatmajan
& Jl. Pajeksan
 - Relocation
 - Parallel Parking on
One side



Jl Suryatmajan



Jl Pajeksan



Ilustrasi

Optimation of Margo Mulyo Roads as Pedestrian Walk



**Entry of Vredeburg
Fortress & National Palace**

**Tourists who wants
to go to titik nol :**

- Tourists who wants to go to titik nol :
- Car : park at pasar sore (TKP 2) or indra cinemas;
- Motorcycle : park at post office, mirota, TKP 2

**Access to the
national palace is
open when needed**





Optimation of Margo Mulyo Steet as Car free Day Area and Pedestrian Walk



- Street Operation & Event Management

- Street Management when Being Closed

- Musical Event;
 - Art Exhibition;
 - Reguler Event; etc

- Preservation and *enforcement*

- Sanitation
 - Security
 - Sublimity



copyright (c) Luzviminda and Sunarya



Impacts of the good practice



Communities have a space to express themselves



Pedestrian could walk with ease, without being disturbed by vehicle and parking area



Fresh Air



Ensure sustainability of the practice?



Making Rules and Regulations about:



Non Motorized Transportation Area



Parking Management



Area Management

The Main Lessons Learned of Practice Implementation



**Social and Economic Problem are more difficult
To solve than Technical Problem**



The First Steps to Take:

